

4/5




FIG. 6



Applicant: Paillaman et al.; Serial No. 10/065,516; Atty Dkt. No. 24-NS-123144; Title
METHOD OF DETECTING CRACKS IN JET PUMP BEAMS OF A NUCLEAR
REACTOR; Attorney: John S. Beulick, Armstrong Teasdale LLP, One Metropolitan
Square, Suite 2600, St. Louis, MO 63102; 314-621-5070

5/5




FIG. 7

10/065,516